



Service Bulletin

S.B. No: 143

Title:

FAIREY HYDRAULICS MAIN UNDERCARRIAGE BACKLASH CHECK

Classification:

This Service Bulletin has been classified by SAL Highly Recommended

Compliance:

At next Annual Inspection

Issue 2 adds note to Para 1 and Fig 1 to hold torque links rigid.

Applicability:

Post Mod M468 equipped aircraft T67B, T67C Series, T67M, T67M-MkII and T67M200

INTRODUCTION:

Cases have been reported of Fairey Hydraulics main undercarriage displaying movement between the stub and the leg.

This SB requires a one time inspection.

ACTION:

- 1. Support aircraft safely on jacks and remove main wheel and tyre assembly. Ensure torque links are held rigidly during loading.
- 2. Measure 7 ins along the stub axle from the centreline of the plunger tube. See Figure 1.
- 3. Set up dial indicator for up and down checks at the 7 ins position.
- 4. Establish a means to record the neutral position and zero the indicator.
- Apply 2 lbs of force upwards. Measure and record the deflection.
- 6. With stub axle back to the neutral position and indicator set to zero, apply 2 lbs of force downwards. Measure and record the deflection.
- Total deflection up and down must not exceed 0.020 ins.
- 8. Set up the equipment to record fore and aft deflections at the same 7 ins mark. Zero the indicator.
- 9. Apply 2 lbs of force forward. Measure and record the deflection.

Approved by: For and on behalf of SLINGSE	ANU DIMITED	Date:	9 13 199	Issue 2
Kirkbymoorside, York. YO62 6EZ Fax No: 01751 431173	Tel: 01751 432474 E-mail: SAL5@Slingsby co.uk	Page	1 of 3	

A Cobham plc company

ISSUED 0 9 MAR 1999



S.B. No: 143

Issue: 2

Page 2 of 3

- 10. With stub axle back to the neutral position and indicator set to zero, apply 2 lbs of force rearwards. Measure and record the deflection.
- 11. Total deflection forwards and rearwards must not exceed 0.040 inches.
- 12. If either of the requirements for maximum allowable deflection are not met, moving strut and stub assembly should be returned to manufacturer for inspection.
- 13. Annotate Log Book "SB 143 complied with"
- 14. The Maintenance Manual is in the process of being amended.

For replacement parts and/or if in doubt, contact SAL Product Support Department.



S.B. No: 143

Issue: 2

Page 3 of 3




Fig 1 PLACEMENT OF DIAL INDICATOR