

SERVICE BULLETING

SB No. 014

Issue No. 1

TITLE

BEARINGS IN CONTROL COLUMN AILERON TIE ROD

CLASSIFICATION

This has been classified as Mandatory by CAA

COMPLIANCE

At next 50 hour inspection

APPLICABILITY:

All T67A, B, M, M-MkII, and M200 aircraft.

INTRODUCTION:

An isolated occurrence has been reported of the 4 bearings in the control column aileron tie rod coming loose in their housings.

ACTION:

- 1. Remove port and starboard control column gaiters.
- Inspect, using a torch and mirror as necessary, the 4 bearings in the control column aileron tie rod for correct locations in their housings. See sketch.
- 3. If any bearings are loose or out of position, proceed as follows:
 - 3.1 Remove seats for method see Maintenance Manual Section 3.4.1 which includes seat removal. Ref. GRP aircraft. For T67As remove seats, centre consoles and control covers.
 - 3.2 Remove control column tie rod.
 - 3.3 Reassemble the bearings to their housings using Loctite Studiock 270 adhesive, and "centre punch" in 3 places at 120° pitch on both sides.

N.B. Check inner ball for full and free movement.

- 3.4 Refit rod and seats by reverse action of 3.2 and 3.1 above.
- 4. Annotate aircraft log book Service Bulletin No. 014 satisfied
- 5. If bearings were loose or out of position, advise the undersigned as soon as possible.

MOD M 302 A/B

ISSUED

ISSUED BY:

363

Date 5-1-87

Page

2



SERVICE BULLETIN MIIII

SB No. 014

Issue No. 1

TITLE

BEARINGS IN CONTROL COLUMN AILERON TIE ROD


CLASSIFICATION

This has been classified as Mandatory by CAA

COMPLIANCE

At next 50 hour inspection

- CONTROL COLUMNS REF -



CENTRE PUNCH EACH BEARING 3 TIMES AT 120° PITCH BOTH SIDES

VIEW SHOWING RELEVANT BEARINGS

ISSUED BY:

Date

FOR CLARITY

for and on behalf of SLINGSBY AVIATION PLC