

INFORMATION BULLETIN

Serial No. 006

Aircraft Type T67B, C, D, M, M-MkII, M200

TITLE

WIRELOCKING OF RUDDER PEDALS (UPPER PIVOT)


This Information Bulletin advises that Mod Bulletin for Modification M162 has been raised to Issue 3.

Compliance is required within 20 flying hours. Note also that SB 008, Issue 2 included, requires the inspection prior to incorporation of Mod M162 to be done on a daily basis.

In many cases Mod M162 has already been carried out - in which case no further action is required, except to add the final paragraph of Issue 3 to Section 22 of the original Mod Bulletin. The appropriate section of the Maintenance Manual will be updated and distributed as soon as possible.

To ensure that all operators are in receipt of all appropriate documentation this Information Bulletin is accompanied by:

Mod Bulletin M162 Issues 1, 2, & 3
Service Bulletin SB 008 Issues 1 and 2.

ISSUED BY:

Date 20.11.85

for and on behalf of **SLINGSBY AVIATION LIMITED**
Kirkbymoorside, York YO6 6EZ, England Tel 0751 31751 Telex 57597

Page 1 of 1