



Information Bulletin

I.B. No: 037

Title: LYCOMING SB NO 566 CRANKSHAFT REPLACEMENT IN LYCOMING ENGINES

Compliance: Compliance is required as detailed in Textron Lycoming Service Bulletin No. 566

Applicability: T67M200, T67M260 and T67M260-T3A. Works Numbers 2066 and subsequent not applicable.

Lycoming has continued to analyse crankshafts in service. This analysis indicates that the replacement of certain crankshafts is warranted. Therefore, Lycoming is recalling certain crankshafts in the specified four and six cylinder engines.

Please refer to Service Bulletin 566, downloadable from the Internet on www.lycoming.textron.com, or obtainable from relevant aircraft owner.

Any further information, or components required to comply with this Service Bulletin, should be obtained from Textron Lycoming.

Approved by: 	Date: 01.07.06	Issue 1
For and on behalf of SLINGSBY AVIATION LIMITED	Page 1	of 1
Kirkbymoorside, York. YO62 6EZ Fax No: 01751 431173	Tel: 01751 432474 E-mail: SAL5@Slingsby.co.uk	