


SERVICE BULLETIN HIII

Issue No. 3



BEARINGS IN CONTROL COLUMN AILERON TIE ROD

CLASSIFICATION

This S.B. has been classified as Mandatory by CAA

COMPLIANCE

At next 50 hr inspection and 150 hr inspections thereafter until action 3.3, Ref Issue 2 of this S.B. or Mod M302 incorporated

For further information and/or Modification Bulletin contact Product Support Manager at address quoted at bottom of this page.

Please refer to Issue 2 of this Service Bulletin.

The following have been added.

".....until Action 3.3"

"For further information"

ISSUED BY:

02 C 32

Date 14. 3.88

for and on behalf of SLINGSBY AVIATION PLC .
Kirkbymoorside York YO6 6EZ England Tel 0751 32474 Telex 57597

Page

of