

# SERVICE BULLETIN

SB No. 030

Issue No. 1

**TITLE**

AILERON FLETTNER STRIPS

**CLASSIFICATION**

This Service Bulletin has been classified as Optional by the U.K. C.A.A.

**COMPLIANCE**

See below.

APPLICABILITY

All T67M, T67M-MkII and T67M200 except Works Nos. 2043, 2062, 2066 and subsequent Works Numbers.

INTRODUCTION:

A small number of cases have occurred of aileron low frequency oscillations at high air speeds, which is easily damped out by slight lateral pressure on the control column.

ACTION:


If such aileron oscillation occurs then Mod 387 should be incorporated.

Note: Mod M387 Modification Bulletin and Mod Kit are available from Slingsby Aviation Ltd, Product Support Department.

24 MAY 1989

**ISSUED**

ISSUED BY:




 Date 23<sup>rd</sup> May 1989

for and on behalf of SLINGSBY AVIATION PLC

Kirkbymoorside, York YO6 6EZ England Tel 0751 32474 Tele 57597

Page

1

of

1