

SERVICE BULLETIN

SB No. 75 Issue No. 2

TITLE

INSPECTION OF RUDDER PEDAL SLIDER/HEATER DISTRIBUTION BOX CLEARANCE

CLASSIFICATION

Highly Recommended

COMPLIANCE

At next 50 hr check or within one month of receipt of bulletin.

With reference to Issue 1:


ACTION

Paragraph 4. T67G-45-851 to read T67G-03-851.

Enclosure:

Service Bulletin SB No.75 Iss 1, if required.

ISSUED BY:



Date 6-4-95

for and on behalf of **SLINGSBY AVIATION LIMITED**
Kirkbymoorside, York YO6 6EZ England Tel 0751 32474 Telex 57597

Page 1 of 1