



SERVICE BULLETIN

SB No.

137

Issue No.

1

TITLE
BENDIX KING SERVICE BULLETIN LISTING
CLASSIFICATION

This Service Bulletin has been classified by SAL as Essential

COMPLIANCE

As requested by each Bendix King Service Bulletin Unless Otherwise Specified.

APPLICABILITY:

T67M260 and T67M260-T3A.

INTRODUCTION:

This Service Bulletin is issued to list all Bendix King Service Bulletins relating to Bendix King Avionics as used on the Slingsby T67M260 and T67M260-T3A Firefly.

This Service Bulletin will be updated periodically to add further Bendix King Service Bulletins when received.

ACTION:

Operators are to ensure they have a complete set of the relevant Bendix King Service Bulletins, as per attached list, and that they have complied with them.

For copies of Bendix King Service Bulletins listed, please contact Bendix King.

ATTACHMENTS:

Bendix King Service Bulletins List Issue 1 (1 page)

ISSUED BY:

 for and on behalf of **SLINGSBY AVIATION LIMITED**
 Kirkbymoorside, York YO6 6EZ, England

 Tel. 01751 432474
 Fax 01751 431173

Date

27 Aug 97

Page

1

of

1

SB No	Date	Subject	Applicable to USAF	Applicability	Compliance
KX165-16	Dec 94	Modifications to meet the requirements of ICAO Annex 10 for FM broadcast interference immunity	Yes	VHF Comm Nav KX165-25 Part No. 069-1025-25 Serial No. 54999 and below	Customer option
KN62A-2	Oct 93	Mod to improve AGC operation	Yes	DME KN62A-01 : Part No. 066-1068-01 : Serial No. 36263 and below	Recommended if problem exists
KN62A-3	Oct 93	Mod to improve AGC operation.. Supercedes mod KN62A-2	Yes	DME KN62A-01 : Part No. 066-1068-01 27/08/97 : Serial No. 26782 and below	Units with Mod KN62-3 should have Mod KN62-3 installed
KN62A-5 Rev 1	Dec 95	Mod to provide protection from TACAN interference on the image frequency	Yes	DME KN62A-01 : Part No. 066-1068-01 : Serial No. 27044 and below	Recommended